## Dinex Repair kit 54184-RK Mounting Instructions

Dinex is pleased to introduce the aftermarket with the pipe rep-kit for Renault Midlum. The Repair Kit gives the opportunity to easily repair the pipe without additional costs. In addition to that Dinex offers full range of pipes for Mercedes Axor Euro III. For more information please contact your local sales office.





Dinex no. 78800 Dinex Exhaust Assembly Paste

ecDoc

ERTIFIED DATA SUPPLIER







Exhaust

*Quality products from Dinex – Europe's leading supplier of complete exhausts systems and emission technologies for commercial vehicles.* 

Repair kit for 54184 - Mercedes Axor OE 941.490.0919

1. Cut the pipe as close as possible to the flex hose and make sure that is not less than 380 mm from pipe end.

Before connecting the pipes

apply Dinex

 Make sure that there is 385 mm distance from clamp to pipe end as per drawing, while the flex is fully

2.

2. APPLY THE PASTE\*

3. CONNECT

uniformly

compressed.

Assembly Paste (78800).











## going the extra mile